



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
PHASE 1 RESIDENCE BUILDINGS														
ASPEN HALL														
A1	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					
A2	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3490 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	BASEMENT	DRYWALL JOINT COMPOUND	WATER DAMAGED	WALL	6 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05 IN CONJUNCTION WITH EACC LEVEL 1 MOULD PROCEDURES.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving.
 C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
A3	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	ROOM A-3-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	CEILING	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM A-3-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	CEILING	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L. FT.	P1-2 (A-C) (2010 Report)			ND	NO				

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
A4	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	WASHROOM - BASEMENT	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM A-4-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM A-4-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	ABOVE KITCHEN SINK	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
A4	ROOM A-4-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	ABOVE KITCHEN SINK	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
A5	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3498 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	LIVING ROOM	DRYWALL JOINT COMPOUND	WATER DAMAGED DRYWALL	WALL	3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REMOVED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM A-5-F	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT. + 2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REMOVED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
A5	ROOM A-5-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REMOVED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
A6	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3496 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
A7	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS									ALL ASBESTOS-CONTAINING CAULKING ON EXTERIOR WAS REMOVED IN 2023 (OHE PROJECT #28878).	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	UNKNOWN	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	ALL ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND WAS REMOVED IN 2023 WITH THE EXCEPTION OF THE BASEMENT (OHE PROJECT #28878).	4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	BASEMENT	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	ALL ORIGINAL LIGHT FIXTURES WERE REMOVED IN 2023 WITH THE EXCEPTION OF THE BASEMENT (OHE PROJECT #28878).	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without movement.
- C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
A8	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3497 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	CLOSET - THIRD FLOOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
A9	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3499 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	ROOM A-9-F	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	4 L. FT. + 3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
A9	CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM A-9-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	4 L. FT. + 3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THIRD FLOOR CLOSET	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	LIVING ROOM + KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL BULKHEAD	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)			ND	NO				

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving furniture.
 C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
A10	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
A11	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to building structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
BIRCH HALL														
B1	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3490 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	ROOM B-1-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM B-1-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	LIVING ROOM + KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)			ND	NO				

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B2	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYBOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYBOTILE	YES	GOOD	A	FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	CEILING	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYBOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	4
	ROOM B-2-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYBOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to building structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B2	ROOM B-2-1	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	SECOND FLOOR LANDING	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	CEILING	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	SECOND FLOOR CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B3	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSTOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSTOTILE	YES	GOOD	A	FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	ROOM B-3-F	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL NEAR FLOOR	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSTOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM B-3-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL NEAR FLOOR	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSTOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B4	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	FRIABLE		4
	ROOM B-4-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL NEAR FLOOR	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					
B5	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3498 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to building structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B5	KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM B-5-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL NEAR FLOOR	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THIRD FLOOR LANDING	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL UNDER LANDING	1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THIRD FLOOR CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	<1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B6	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3495 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	STORAGE ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THIRD FLOOR LANDING	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to building structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B6	ROOM B-6-F	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
				WALL NEAR CEILING	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM B-6-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	1 L. FT. + 1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM B-6-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without moving furniture.
- C - Accessible only to maintenance staff and concealed from view due to furniture or other obstructions.

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required	
B7	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A	
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSTILE	YES	GOOD	A	NON-FRIABLE		4	
	ROOM B-7-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	<1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	SECOND FLOOR CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL NEAR CEILING	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	ROOM B-7-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	4 L. FT.	P1-1a (2010 Report)	1.5	CHRYSTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	N/A	
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO						N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4	

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
B8	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3499 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	BASEMENT STORAGE ROOM	DRYWALL JOINT COMPOUND	MOULD IMPACTED	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05 IN CONJUNCTION WITH EACC LEVEL 1 MOULD PROCEDURES.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
CEDAR HALL														
C1	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to ;3

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required	
C2	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A	
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3485 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4	
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4	
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO						N/A
	ROOM C-2-F	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	<1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	BASEMENT WASHROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
ROOM C-2-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2		

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
C3	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	SECOND FLOOR CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM C-3-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	3 L. FT. + 1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
C3	ROOM C-3-K	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THIRD FLOOR WASHROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	3 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					
C4	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3496 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	BASEMENT STAIRS	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
C4	ROOM C-4-F	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM C-4-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
C5	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3475 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to building structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
C6	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	STORAGE ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM C-6-F	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	4 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM C-6-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required	
C6	ROOM C-6-I	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	4 L. FT. + 3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	ROOM C-6-J	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	4 L. FT. + 1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.		
	ROOM C-6-K	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	4 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO						N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE			4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED		4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO						N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving furniture.
 C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
C7	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM • KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	DRYWALL EDGE	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	SECOND FLOOR WASHROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	DRYWALL	4 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM C-7-1	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	DRYWALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
C7	THIRD FLOOR WASHROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	DRYWALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO	GOOD	A	NON-FRIABLE		N/A
C8	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3495 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM • KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	8 L. FT. + 1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	STORAGE ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
C8	KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	6 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
C8	LIVING ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM C-8-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM C-8-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without movement.
- C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
DOGWOOD HALL														
D1	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3496 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	FRONT ENTRANCE	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM D-I-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)			ND	NO				

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
D2	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3497 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL ABOVE SINK	1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	LIVING ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	SECOND FLOOR BATHROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL ABOVE BATHTUB	4 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without moving furniture.
- C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
D3	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3495 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	3 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THIRD FLOOR CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)			ND	NO				

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
D4	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					
D5	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL NEAR CEILING	1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	LIVING ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving furniture.
 C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
D5	MAIN ENTRANCE	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	1 SQ. FT. + 1 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
D6	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
D7	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving furniture.
 C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
D7	SECOND FLOOR CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
D8	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM • KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL EDGE	2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
D8	ROOM D-8-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
D9	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878), ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	SECOND FLOOR WASHROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM D-9-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required	
D9	STAIRS	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL ADJACENT TO STAIRS	5 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A	
ELM HALL															
E1	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A	
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4	
	KITCHEN	DRYWALL JOINT COMPOUND	WATER DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2	
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED		N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)			ND	NO					N/A

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without mov
- C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regula
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
E2	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
E3	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3490 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM • KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED EDGING	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving furniture.
 C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
E4	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	LIVING ROOM	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05 IN CONJUNCTION WITH EACC LEVEL 1 MOULD PROCEDURES.	2
					2 L. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM E-4-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	2 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
E5	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3497 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	SECOND FLOOR CORRIDOR	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05 IN CONJUNCTION WITH EACC LEVEL 1 MOULD PROCEDURES.	2
	ROOM E-5-H	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM E-5-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
E6	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	SECOND FLOOR LANDING	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	CEILING BULKHEAD OF STAIRCASE LANDING	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	LIVING ROOM • KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)			ND	NO				

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement
 C - Accessible only to maintenance staff and concealed from view due to structure

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
E7	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	LIVING ROOM + KITCHEN	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	ROOM E-7-G	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	STAIRS	DRYWALL JOINT COMPOUND	DAMAGED DRYWALL	WALL ADJACENT TO STAIRS	<1 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	POOR	A	NON-FRIABLE	THE DAMAGED DRYWALL WITH ASBESTOS-CONTAINING DRYWALL JOINT COMPOUND SHOULD BE REPAIRED FOLLOWING TYPE 1 ASBESTOS PROCEDURES, AS PRESCRIBED UNDER O. REG. 278/05.	2
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to building structure.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
E8	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3494 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
E9	EXTERIOR	WINDOW CAULKING	WHITE CAULKING	EXTERIOR WINDOWS	UNKNOWN	28878-1C	1	CHRYSOTILE	PRESUMED	GOOD	A/B	NON-FRIABLE	SAMPLED FROM UNIT A7 BY OHE IN 2023 (PROJECT #28878). ASBESTOS-CONTAINING WINDOW CAULKING IS PRESUMED TO BE PRESENT ON THE EXTERIOR OF OTHER PHASE 1 RESIDENCES.	N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-1a (2010 Report)	1.5	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE		4
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
PHASE 2 RESIDENCE BUILDINGS														
FIR HALL														
ALL	THROUGHOUT	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	THROUGHOUT BUILDING	UNKNOWN	02 (A-C) (2013 REASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
F1	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	GROUND FLOOR - ENTRANCE CORRIDOR	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	SMALL CLOSET	6 SQ. FT.	02 (A-C) (2013 RE-ASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement.
 C - Accessible only to maintenance staff and concealed from view due to obstructions.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



Historic Asbestos-Containing Materials Data University of Toronto Scarborough Phase 1 and Phase 2 Residences

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
F2	THROUGHOUT	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	THROUGHOUT BUILDING	UNKNOWN	02 (A-C) (2013 REASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
F3	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
F4	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to ;3

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
F4	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
	GROUND FLOOR - ENTRANCE CORRIDOR	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	SMALL CLOSET	6 SQ. FT.	02 (A-C) (2013 RE-ASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
F5	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
F6	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	GROUND FLOOR - ENTRANCE CORRIDOR	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	SMALL CLOSET	2 SQ. FT.	02 (A-C) (2013 RE-ASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	NOT OBSERVED DURING 2020 REASSESSMENT	4

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without mov2
- C - Accessible only to maintenance staff and concealed from view due to ;3

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regula
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
F7	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
	GROUND FLOOR - ENTRANCE CORRIDOR	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	SMALL CLOSET	6 SQ. FT.	02 (A-C) (2013 RE-ASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
F8	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
F9	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
F9	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
F10	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
F11	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
	GROUND FLOOR - ENTRANCE CORRIDOR	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	SMALL CLOSET	6 SQ. FT.	02 (A-C) (2013 RE-ASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without movement.
- C - Accessible only to maintenance staff and concealed from view due to building structure.

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
GREY PINE HALL														
ALL	THROUGHOUT	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	THROUGHOUT BUILDING	UNKNOWN	02 (A-C) (2013 REASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
G1	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G2	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without mov2
- C - Accessible only to maintenance staff and concealed from view due to ;3

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regula
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G3	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G4	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G5	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to ;3

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G6	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G7	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G8	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
G9	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
HICKORY HALL														
ALL	THROUGHOUT	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	THROUGHOUT BUILDING	UNKNOWN	02 (A-C) (2013 REASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
H1	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
H2	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
H3	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
H4	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving furniture.
 C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
H5	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
H6	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
H7	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without moving furniture.
 C - Accessible only to maintenance staff and concealed from view due to furniture.

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
H8	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
H9	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
H10	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
IRONWOOD HALL														
ALL	THROUGHOUT	VINYL FLOOR TILES WITH YELLOW MASTIC	12"X12" TAN VINYL FLOOR TILES WITH BROWN STREAKS AND YELLOW MASTIC	THROUGHOUT BUILDING	UNKNOWN	02 (A-C) (2013 REASSESSMENT)	1.0-1.2	CHRYSOTILE	YES	GOOD	A	NON-FRIABLE	THE MASTIC WAS ALSO ANALYZED AND DETERMINED TO BE NON-ASBESTOS. THESE TILES MAY BE PRESENT IN OTHER PHASE 2 RESIDENCE BUILDINGS IN CONCEALED AREAS (I.E., BENEATH CARPETS AND NEWER FLOORING LAYERS).	4
I1	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
I2	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

- A - Accessible and exposed to all occupants of the building.
- B - Accessible only to maintenance staff and exposed to view without mov2
- C - Accessible only to maintenance staff and concealed from view due to ;3

Level of Action Required

- 1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
- 2 - Perform asbestos removal/repair for compliance with the regulations.
- 3 - Type 2 asbestos procedures required to enter area.
- 4 - Regular inspection/surveillance of ACM for compliance with the regula
- N/A - Not applicable.

Definitions

- ACM - Asbestos-Containing Materials
- SA - Sample representative
- R-SA - Sample referenced to a visually similar homogeneous sample material.
- ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
13	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
14	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A
15	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without mov2
 C - Accessible only to maintenance staff and concealed from view due to

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regula
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected



**Historic Asbestos-Containing Materials Data
University of Toronto Scarborough
Phase 1 and Phase 2 Residences**

Unit#	Area	Material	Description	Location	Qty/Unit	Sample Number	%	Type	ACM (Yes, No, Suspect)	Condition	Accessibility	Friability	Comments	Action Required
16	EXTERIOR	CAULKING	BROWN CAULKING	EXTERIOR WINDOWS, DOORS & TRIM	45 L.FT.	P2-3(A-C) (2010 Report)	0.25	CHRYSOTILE	NO				TRACE ASBESTOS DETECTED. MATERIAL NOT CONSIDERED TO BE ASBESTOS-CONTAINING.	N/A
	INTERIOR - WINDOWS AND DOORS	PERIMETER CAULKING	VARIOUS CAULKING APPLICATIONS - INTERIOR	PERIMETER OF WINDOWS AND DOORS - INTERIOR	45 L.FT.	P2-2(A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	LIGHT FIXTURE	HEAT SHIELD PAPER	THROUGHOUT BUILDING	UNKNOWN	NOT SAMPLED	N/A	PRESUMED	PRESUMED	GOOD	D	FRIABLE	PRESUMED ACM, NOT PREVIOUSLY SAMPLED	4
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	3500 SQ. FT.	P1-2 (A-C) (2010 Report)		ND	NO					N/A
	THROUGHOUT	DRYWALL JOINT COMPOUND	WHITE DRYWALL JOINT COMPOUND	WALLS AND CEILINGS	SEE ABOVE	01 (A-D) (2013 ACM RE-ASSESSMENT)		ND	NO					N/A

Level of Accessibility

A - Accessible and exposed to all occupants of the building.
 B - Accessible only to maintenance staff and exposed to view without movement
 C - Accessible only to maintenance staff and concealed from view due to structure

Level of Action Required

1 - Immediate clean-up of fallen ACM/debris likely to be disturbed.
 2 - Perform asbestos removal/repair for compliance with the regulations.
 3 - Type 2 asbestos procedures required to enter area.
 4 - Regular inspection/surveillance of ACM for compliance with the regulations.
 N/A - Not applicable.

Definitions

ACM - Asbestos-Containing Materials
 SA - Sample representative
 R-SA - Sample referenced to a visually similar homogeneous sample material.
 ND - None detected