

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR =

0

Building Name	Site Address	City
Portable 102	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 10, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1		102 SOUTH	5/ABC	262167	2010	2022	2028	Y	
2		102 SOUTH	5/ABC	261134	2010	2022	2028	Y	
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR =

Building Name	Site Address	City
Social Sciences	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 10, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	1	Outside Room MW100	10/ABC	703910	2005	2029	2023	Y	RECOMMEND 2D SIGN
2	1	East Outside MW129	10/ABC	194391	2005	2029	2023	Y	RECOMMEND 2D SIGN
3	1	Northeast in MW102 via MW100 B KEY	10/ABC	495857	2014		DUE	Y	DUE TO 6YEARS MAINT. RECOMMEND 2D
4	1	South at Stair 2	5/ABC	21280838	2021	2033	2027	Y	RECOMMEND 2D SIGN
5	1	South in MW146 via Stair 2 (Sprinkler Room)	10/ABC	196781	2004	2028	2022	Y	RECOMMEND 2D SIGN
6	1	West Outside MW170	10/ABC	703901	2005	2029	2023	Y	RECOMMEND 2D SIGN
7	2	Outside MW219	10/ABC	194290	2004	2028	2022	Y	
8	2	Inside MW215	10/ABC	196776	2004	2028	2022	Y	RECOMMEND 2D SIGN
9	2	North at Stair 1	10/ABC	194293	2004	2028	2022	Y	RECOMMEND 2D SIGN
10	2	South at Stair 2	10/ABC	194299	2004	2028	2022	Y	RECOMMEND 2D SIGN
11	2	West in MW266	10/ABC	196782	2004	2028	2022	Y	
12	2	West Outside MW270	10/ABC	194292	2004	2028	2022	Y	RECOMMEND 2D SIGN
13	3	East in MW317	10/ABC	52861655	2021	2033	2027	Y	
14	3	East in MW317A - ELEV RM	10/ABC	52864749	2021	2033	2027	Y	
15	3	East Outside MW319	10/ABC	196783	2004	2028	2022	Y	RECOMMEND 2D SIGN
16	3	Northeast at Stair 1	10/ABC	52861677	2021	2033	2027	Y	RECOMMEND 2D SIGN
17	3	Southeast at Stair 2	10/ABC	194291	2004	2028	2022	Y	RECOMMEND 2D SIGN
18	3	West Outside MW373	10/ABC	194322	2004	2028	2022	Y	RECOMMEND 2D SIGN+ Broken/Missing Latch
19	PH	Center	10/ABC	194295	2004	2028	2022	Y	
20	PH	North at Stair 1	10/ABC	52861662	2021	2033	2027	Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
21	PH	North in Electrical Room	10/ABC	196774	2004	2028	2022	Y	
22	PH	South at Stair 2	10/ABC	196772	2004	2028	2022	Y	
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									
34									
35									
36									
37									
38									
39									
40									
41									
42									
43									
44									
45									

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR = 0

Building Name	Site Address	City
HUMANITIES WING	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 10, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR N	MAY 2023 Inspections	REMARKS
1	1	East in Room HW102	5/CO2	73510907	2017	2022		Y	
2	1	East in Room HW103E	5/ABC	315248	2008	DUE		Y	DUE TO H-TEST
5	1	East in Room HW104	5/ABC	66733543	2016	2028	2022	Y	
6	1	East in Room HW105	10/ABC	44511	2007	2031	2025	Y	
7	1	East in Room HW109 ELEV RM	10/ABC	52857637	2021	2033	2027	Y	
8	1	West n Room HW110 Key (AA)	5/ABC	44722	2003	2031	2025	Y	
3	1	East in Room HW110	5/ABC	21280782	2021	2033	2027	Y	
4	1	East in Room HW112	10/ABC	7123260	2021	2033	2027	Y	
9	1	West in Room HW113 - KEY	5/ABC	21280788	1987			Y	
10	1	West Outside Room HW115	5/ABC	839273	2010	2022	2028	Y	
11	1	West Outside Room HW115	Hose100C	~	2021	2026		Y	
12	2	East Outside Room HW214	5/ABC	40365	2002		DUE	Y	DUE TO 6 YEARS. RECOMMEND 2D SIGN
13	2	East Outside Room HW214	Hose100C	~	2021	2026		Y	
14	2	East Outside Room HW216	5/ABC	839274	2010	2022	2028	Y	
15	2	East Outside Room HW216	Hose100C	~	2021	2026		Y	
16	2	Cafeteria - Kitchen Area by Fryer	6I Kclass	9816115	2016	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
17	2	HW202 Entrance into Kitchen from Osmows	6L Kclass	104730436	2023	2028	2034	Y	*New* Triangle Fire
18	2	West in Cafeteria behind Pasta by HW202	6I Kclass	9816113	2016	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
19	2	West in Cafeteria behind Pasta by HW202	10/ABC	507099	2012			Y	RECOMMEND 2D SIGN
20	2	West in Cafeteria by Cash	5/ABC	39253809	2015		DUE	Y	DUE TO 6 YEARS. RECOMMEND 2D SIGN
21	2	Chopsticks (Wall by fryer)	6L Kclass	104730468	2023	2028	2034	Y	*New* Triangle Fire
22	2	Cafeteria Chopstick	6L K	98116114	2016	2028	2022	Y	RECOMMEND 2D SIGN
23	2	West in HW2 Tim Hortons Kitchen	5/ABC	680828	2012	2024	2030	Y	RECOMMEND 2D SIGN
24	2	Kitchen Sink	6L Kclass	10473519	2023	2028	2034	Y	*New* Triangle Fire
25	2	West in HW202 by Kitchen Handwash Sink	10/BC	893101	2005	2024		Y	RECOMMEND 2D SIGN
26	2	West in HW202 in Tim Hortons Storage Room at Exit	5/ABC	143749	2006	2030	2024	Y	RECOMMEND 2D SIGN
27	2	West in GW202 Outside Room HW205	5/ABC	680831	2012	2024	2030	Y	RECOMMEND 2D SIGN
28	2	West in GW202 Outside Room HW205	Hose100C	~	2012	DUE		Y	DUE TO H-TEST
29	2	West Outside Room HW200	5/ABC	39253777	2015		DUE	Y	DUE TO 6 YEARS. RECOMMEND 2D SIGN

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR	MAY 2023 Inspections	REMARKS
30	2	West Outside Room HW200	Hose100C	~	2021	2026	2032	Y	
31	3	Center at Stair A	5/ABC	839263	2010	2022	2028	Y	
32	3	Center at Stair A	Hose100C	~	2021	2026		Y	
33	3	Center in Room HW305(MA)	5/ABC	21280812	2021	2033	2027	Y	
34	3	Center in Room HW305(MA)	Hose100C	~	2021	2026		Y	
35	3	East at Stair B	5/ABC	839271	2010	2022	2028	Y	RECOMMEND 2D SIGN
36	3	East at Stair B	Hose100C	~	2021	2026		Y	
37	3	Northwest in Room HW302 Outside Room HW302F	5/ABC	2400	1993	2029	2023	Y	
38	3	Northwest in Room HW302 Outside Room HW302F	Hose100C	~	2017	2022		Y	
39	3	West Outside Room HW300	5/ABC	893275	2010	2022	2028	Y	
40	3	West Outside Room HW300	Hose100C	~	2021	2026		Y	
41	4	Center at Stair A	10/ABC	576027	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
42	4	Center at Stair A	Hose100C	~	2021	2026		Y	
43	4	Center in Room HW437A	5/ABC	7123267	2022			Y	OBsolete - TOO OLD. RECOMMEND 2D SIGN
44	4	East at Stair B	10/ABC	52861651	2021	2033	2027	Y	
45	4	East at Stair B	Hose100C		2021	2026		Y	RECOMMEND 2D SIGN
46	4	East in Room HW434A	5/CO2	73510904	2017	2029	2023	Y	
47	4	Northwest Outside Room HW404A	5/ABC	144215	2006	2030	2024	Y	RECOMMEND 2D SIGN
48	4	Northwest Outside Room HW404A	Hose100C	~	2021	2026		Y	
49	4	West Outside Room HW400	5/ABC	21280815	2021	2033	2027	Y	RECOMMEND 2D SIGN
50	4	West Outside Room HW400	Hose100C	~	2021	2026		Y	
51	5	Center at Stair A	5/ABC	839229	2010	2022	2028	Y	RECOMMEND 2D SIGN
52	5	Center at Stair A	Hose100C	~	2021	2026		Y	
53	5	East at Stair B	5/ABC	675167	2012			Y	RECOMMEND 2D SIGN
54	5	East at Stair B	Hose100C	~	2021	2026		Y	
55	5	Northwest in Room HW502	10/ABC	648858	2012	2024	2030	Y	RECOMMEND 2D SIGN
56	5	Northwest in Room HW502	5/ABC	7123247	2022			Y	OBsolete - TOO OLD. RECOMMEND 2D SIGN
57	5	Northwest Outside Room HW502	5/ABC	143758	2006	2030	2024	Y	RECOMMEND 2D SIGN
58	5	Northwest Outside Room HW502	Hose100C	~	2021	2026		Y	

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR =

0

Building Name	Site Address	City
Academic Resource Centre	1265 MILITARY TRAIL	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 10, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	2	East Outside Room AC219	5/ABC	815234	1990		DUE	Y	DUE TO 6YEARS MAINT
2	2	East Outside Room AC219	Hose100C	~	2021	2026		Y	
3	2	South in Library North at Exit Adj. AC256	5/ABC	808592	1990		DUE	Y	DUE TO 6YEARS MAINT
4	2	South in Library North at Exit Adj. AC256	Hose100C	~	2021	2026		Y	
5	2	South in Library in 200A Electrical Room Adj AC284 LAN	5/CO2	11040247	2020	2025		Y	
6	2	South in Library in AC284 LAN Room	Hose100C	~	2021	2026		Y	
7	2	South in Library in AC284 LAN Room	5/CO2	73510922	2017	2022		Y	
8	2	South in Library North at Exit Adj. AC258	10/ABC	710776	2004	2028	2022	Y	
9	2	South in Library North at Exit Adj. AC258	Hose100C	~	2021	2026		Y	
10	2	South in Library North at Exit Adj. AC264	5/ABC	310165	2009	DUE		Y	DUE TO H-TEST
11	2	South in Library North at Exit Adj. AC264	Hose100C	~	2021	2026		Y	
12	2	South in Library Northwest Adj. AC270	5/ABC	710575	2004	2028	2022	Y	
13	2	South in Library Northwest Adj. AC270	Hose100C	~	2021	2026		Y	
14	2	AC276	5/ABC	7097886	2012	2024	2030	Y	
15	2	AC276	Hose100C	~	2021	2026		Y	
16	2	South in Library South by Elevator	5/ABC	808607	1990		DUE	Y	DUE TO 6YEARS MAINT

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
17	2	South in Library South by Elevator	Hose100C	~	2021	2026		Y	
18	2	South in Library S/E in Cleaners Room Adj. Electrical Room	5/CO2	679949	2014	2024		Y	IN ELEVATOR ROOM
19	2	South in Library S/E in Electrical Room AC246	5/CO2	309554	2022	DUE		Y	DUE TO H-TEST
20	2	Between AC 283 and AC 284	5/ABC	7097879	2022		DUE	Y	
21	2	Between AC 283 and AC 284	Hose100C	~	2021	2026		Y	
22	2	Southeast at Emergency Exit	10/ABC	21280785	2021	2033	2027	Y	
23	2	Southeast at Emergency Exit	Hose100C	~	2021	2026		Y	
24	2	Southeast Outside AC223	10/ABC	709470	2004	2028	2022	Y	
25	2	Southeast Outside AC223	Hose100C	~	2021	2026		Y	
26	2	Southwest in AC207 (UTSC_IT)	5/ABC	695239	2008	DUE		C	DUE TO H-TEST
27	2	Southwest in AC207 (UTSC_IT)	Hose100C	~	2021	2026		C	
28	2	Southwest in AC207 (UTSC_IT)	5/ABC	5545	1998	2022	2028	C	
29	2	Southwest in AC207 (UTSC_IT)	Hose100C	~	2021	2026		C	
30	2	AC 207 A mezz (UTSC_IT)	5/ABC	673264	2012	2024	2030	C	
31	2	Southwest Outside Tim Hortons	5/ABC	808583	1990		DUE	Y	DUE TO 6YEARS MAINT
32	2	Southwest Outside Tim Hortons	Hose100C	~	2021	2026		Y	
33	3	East at Top of Stair by Library Emergency Exit 3rd Floor	5/ABC	368875	2005	2029	2023	Y	
34	3	East at Top of Stair by Library Emergency Exit 3rd Floor	Hose100C	~	2021	2026		Y	
35	3	East in Electrical Room AC325A VIA MENS W/ROOM 3rd Floor	5/CO2	73510921	2017	2029	2023	Y	IN MENS WASHROOM
36	3	Northeast Outside AC334 3rd Floor	5/ABC	195367	2000		DUE	Y	DUE TO 6 YEARS MAINT

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
37	3	Northeast Outside AC334 3rd Floor	Hose100C	~	2021	2026		Y	
38	3	Southeast at Top of Stair 3rd Floor	5/ABC	7123267	2022			Y	OBSOLETE - TOO OLD TO USE
39	3	Southeast at Top of Stair 3rd Floor	Hose100C	~	2021	2026		Y	
40	3	South in Library on 3rd Floor North Exit by Catwalk	5/ABC	21280830	2021	2033	2027	Y	
41	3	South in Library on 3rd Floor North Exit by Catwalk	Hose100C	~	2021	2026		Y	
42	3	South in Library on 3rd Floor N/E at Exit Outside Study Room	5/ABC	21280824	2021	2033	2027	Y	
43	3	South in Library on 3rd Floor N/E at Exit Outside Study Room	Hose100C	~	2021	2026		Y	
44	3	South in Library on 3rd Floor N/E at Exit In Study Room	5/ABC	808560	1990		DUE	Y	DUE TO 6YEARS MAINT
45	3	South in Library on 3rd Floor N/E at Exit In Study Room	Hose100C	~	2021	2026		Y	
46	3	South in Library on 3rd Floor N/W Corner by Shelf 1	5/ABC	808800	1990		DUE	Y	
47	3	South in Library on 3rd Floor N/W Corner by Shelf 1	Hose100C	~	2021	2026		Y	
48	2	South in Library on 3rd Floor N/W Exit by Shelf 7 (Renovation)	5/ABC	808584	1990		DUE	Y	
49	3	South in Library on 3rd Floor N/W Exit by Shelf 7 (Renovation)	Hose100C	~	2021	2026		Y	
50	3	South in Library on 3rd Floor South by Elevator	5/ABC	808561	1990		DUE	Y	DUE TO 6YEARS MAINT
51	3	South in Library on 3rd Floor South by Elevator	Hose100C	~	2021	2026		Y	
52	3	South in Library on 3rd Floor S/W Exit by Shelf 42	5/ABC	7123255	2022			Y	OBSOLETE - TOO OLD TO USE
53	3	South in Library on 3rd Floor S/W Exit by Shelf 42	Hose100C	~	2021	2026		Y	• 0



FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR = 0

Building Name	Site Address	City
ARTS & ADMINISTRATION	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 10, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	PH	By Stair	10/ABC	115951	2004	2028	2022	Y	RECOMMEND 2D SIGN
2	PH	By Stair	Hose100C	~	2017	2022		Y	
3	1	Northeast Outside AA112	5/ABC	168463	2002		DUE	Y	DUE TO 6YEARS MAINT. RECOMMEND 2D
4	1	Northeast Outside AA112	Hose100C	~	2017	2022		Y	
5	1	Northwest Outside AA121	5/ABC	126271	2009	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
6	1	Northwest Outside AA121	Hose100C	~	2017	2022		Y	
7	1	West in AA141 - Accessibility Office	5/ABC	262140	1990	2026	2032	Y	RECOMMEND 2D SIGN
8	1	West in AA141 - Accessibility Office	Hose100C	~	2017	2022		Y	
9	1	South Outside AA105	5/ABC	20204	2001		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
10	1	South Outside AA105	Hose100C	~	2017	2022		Y	
11	2	North at Stair 1	5/ABC	54100	2006	2024	2030	Y	RECOMMEND 2D SIGN
12	2	North at Stair 1	Hose100C	~	2017	2017	2022	Y	
13	2	South at Stair 2	5/ABC	46494	2001		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
14	2	South at Stair 2	Hose100C	~	2017	2022		Y	
15	2	Center by Elevator	5/ABC	808792	2006	2030	2024	Y	RECOMMEND 2D SIGN
16	2	Center by Elevator	Hose100C	~	2017	2022		Y	
17	3	East Outside AA303	5/ABC	627150	2006	2030	2024	Y	RECOMMEND 2D SIGN
18	3	East Outside AA303	Hose100C	~	2017	2022		Y	
19	3	North at Stair 1	5/ABC	808571	2006	2030	2024	Y	RECOMMEND 2D SIGN
20	3	North at Stair 1	Hose100C	~	2017	2022		Y	
21	3	South at Stair 2	5/ABC	808557	2006	2030	2024	Y	RECOMMEND 2D SIGN

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M.	MAY 2023 Inspections	REMARKS
22	3	South at Stair 2	Hose100C	~	2017	2022		Y	
23	4	North at Stair 1	5/ABC	107946	2005	2029	2023	Y	RECOMMEND 2D SIGN
24	4	North at Stair 1	Hose100C	~	2017	2022		Y	
25	4	South at Stair 2	5/ABC	21280790	2021	2033	2027	Y	RECOMMEND 2D SIGN
26	4	South at Stair 2	Hose100C	~	2017	2022		Y	
27	B	East Outside Sprinkler Room	5/ABC	257578	1998	2022	2028	Y	RECOMMEND 2D SIGN
28	B	East Outside Sprinkler Room	Hose100C	~	2017	2022		Y	
29	B	West by Stairwell Exit	5/ABC	257575	1998	2022	2028	Y	RECOMMEND 2D SIGN
30	B	West by Stairwell Exit	Hose100C	~	2017	2022		Y	
32									
33									
34									
35									
36									
37									
38									
39									
40									
41									
42									
43									
44									
45									

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR =

0

Building Name	Site Address	City
SCIENCE RESEARCH	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 17, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	B	East Outside Room SY0001A	5/ABC	496373	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
2	B	North in Room SY032	5/ABC	695119	2017	2029	2023	Y	RECOMMEND 2D SIGN
3	B	North outside Room SY011	5/ABC	500737	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
4	B	Northwest Outside SY032	5/ABC	316109	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
5	B	South at Stair B	5/ABC	369970	2013	2025	2031	Y	RECOMMEND 2D SIGN
6	B	Southeast in SY004 - Drama Department Workshop	5/ABC	496372	2008	DUE		Y	
7	1	East outside Stair to Theatre Box Office	5/ABC	144254	2006	2030	2024	Y	RECOMMEND 2D SIGN
8	1	North in Room SY126	5/ABC	171903	2002	2026	2032	Y	RECOMMEND 2D SIGN
9	1	North in Room SY172	5/ABC	21280797	2021	2033	2027	Y	RECOMMEND 2D SIGN
10	1	Outside South Room SY122	5/ABC	458418	2004	2028	2022	Y	RECOMMEND 2D SIGN
11	1	South Outside Room SY162	5/ABC	500225	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
12	1	South Outside Room SY116	5/ABC	20049	2000	2024	2030	Y	RECOMMEND 2D SIGN
13	1	West in Room SY165	5/ABC	500273	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
14	2	Labs Outside Room SY230	5/ABC	500743	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
15	2	Labs Outside Room SY250	5/ABC	500748	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
16	2	North in Lab 1	5/ABC	155910	2009	2033	2027	Y	RECOMMEND 2D SIGN

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
17	2	North in Lab 6	5/ABC	369467	2013	2025	2031	Y	RECOMMEND 2D SIGN
18	2	Northeast Outside Room SY205	5/ABC	500260	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
19	2	Northwest in Lab 1	5/ABC	155928	2009	2033	2027	Y	RECOMMEND 2D SIGN
20	2	South Outside Room SY246	5/ABC	496368	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
21	2	South Outside Room SY216	5/ABC	500259	2008	DUE		Y	DUE TO H-TEST
22	2	Southwest at Stair C	5/ABC	500302	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
23	3	Outside Room SY316	5/ABC	500739	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
24	3	Room- Lab 5/6	5/ABC	155925	2009	2033	2027	Y	RECOMMEND 2D SIGN
25	3	Outside Room SY330 via Lab 4/5	5/ABC	500239	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
26	3	Outside Room SY346	5/ABC	500741	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
27	3	Lab 3	5/ABC	155926	2009	2033	2027	Y	RECOMMEND 2D SIGN
28	3	Outside Room SY350 Lab 3	5/ABC	500226	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
29	3	Lab 1	5/ABC	315260	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
	3	SY370C Interior Lab	10/ABC	68294	20217	2029	2023	Y	Meeting
30	3	Outside Stair C	5/ABC	500268	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
31	4	Outside Stair C	5/ABC	500232	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
32	4	Outside Stair B	10/ABC	52861661	2021	2033	2027	Y	RECOMMEND 2D SIGN

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR = 1

Building Name	Site Address	City
HIGHLAND HALL	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 17, 2023	5100042597	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	B	B202 SUMP PUMP ROOM B2	10/ABC	93366257	2018	2030	2024	Y	
2	B	Outside Stair D-L00 in Shellspace B1-024	10/ABC	93367114	2018	2030	2024	Y	RECOMMEND 2D SIGN
3	B	Outside Stair D-L00 in Shellspace B1-024	Hose100C	~	2018	2023		Y	
4	B	O/s stair C	10/ABC	93367117	2018	2030	2024	Y	RECOMMEND 2D SIGN
5	B	O/s stair C	Hose100C	~	2018	2023		Y	
6	B	O/S STAIR D	10/ABC	93226412	2017	2029	2023	Y	
7	B	117 security	5/CO2	73510911	2017	2022		Y	
8	B	B-119B Comm Room	10/CO2	517752	2010	DUE		Y	DUE TO H-TEST
9	B	B-124A Sprinkler Room	10/ABC	93366256	2018	2030	2024	Y	
10	B	124 B comms	5/CO2	7590	1995	DUE		Y	DUE TO H-TEST
11	B	HL DB1-015 - ELECTRICAL ROOM	15/CO2	77097979	2018	2023		Y	
12	B	B1-001K Entrance o/s Lecture Hall	10/ABC	93366247	2018	2030	2024	Y	RECOMMEND 2D SIGN
13	B	B1-001K Entrance o/s Lecture Hall	Hose100C	~	2018	2023		Y	
14	B	B1-029 mech room	10/ABC	93367108	2018	2030	2024	Y	
15	B	B123 TRANS RM	15/CO2	77097974	2018	2023		Y	
16	B	B1-001 Lower Lecture Hall o/s Stair B-L00	10/ABC	93366537	2018	2030	2024	N	*Exam
17	B	B1-001 Lower Lecture Hall o/s Stair B-L00	Hose100C	~	2018	2023		N	*Exam
18	B	DB1-023V Student Commons o/s Entrance to Transformer Room	10/ABC	93366867	2018	2030	2024	Y	
19	B	DB1-023V Student Commons o/s Entrance to Transformer Room	Hose100C	~	2018	2023		Y	
20	B	GL-001 Student Commons Study Space o/s Stari I-L00	10/ABC	93366253	2018	2030	2024	Y	RECOMMEND 2D SIGN
21	B	GL-001 Student Commons Study Space o/s Stari I-L00	Hose100C	~	2018	2023		Y	
22	B	DB1-024 Shell Space o/s stair E	10/ABC	93366387	2018	2030	2024	Y	RECOMMEND 2D SIGN
23	B	DB1-024 Shell Space o/s stair E	Hose100C	~	2018	2023		Y	
24	B	HL DB1-026 CARETAKING STORAGE	10/ABC	93367106	2018	2030	2024	Y	
25	B	BLADEN-HIGHLAND TUNNEL NORTH SIDE	10/ABC	52864742	2021	2033	2027	Y	*NEED ACCESS (PART OF POWEHOUSE)
26	B	BLADEN-HIGHLAND TUNNEL SOUTH SIDE	10/ABC	52861660	2021	2033	2027	Y	*NEED ACCESS (PART OF POWEHOUSE)
27	B	B-179 SUMP PIT ELEV ROOM	10/ABC	93366246	2018	2030	2024	Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
28	B	B-179 SUMP PIT ELEV ROOM	5/ABC	675166	2018	2030	2024	Y	
29	1	HL 106	10/ABC	864156	2018	2030	2024	Y	
30	1	HL 106	Hose100C	~	2018	2023		Y	
31	1	Stair A-L01	10/ABC	93366254	2018	2030	2024	Y	RECOMMEND 2D SIGN
32	1	Stair A-L01	Hose100C	~	2018	2023		Y	
33	1	Kitchen 127	5/ABC	985782250	2020	2032	2026	Y	
34	1	HL D107 - COMM	15/CO2	77097976	2018	2023		Y	
35	1	HL D103 - ELECTRICAL ROOM	15/CO2	77097972	2018	2023		Y	
36	1	o/s room 156	10/ABC	93366384	2018	2030	2024	Y	RECOMMEND 2D SIGN
37	1	o/s room 156	Hose100C	~	2018	2023		Y	
38	1	O/s room 139	10/ABC	93367119	2018	2030	2024	Y	RECOMMEND 2D SIGN
39	1	O/s room 139	Hose100C		2018	2023		Y	
40	1	170 electrical	15/CO2	77097977	2018	2023		Y	
41	GL	HL DGL-001 STUDENT COMMONS - 1 LOWER	10/ABC	93366931	2018	2030	2024	Y	RECOMMEND 2D SIGN
42	1	HL DGL-001 STUDENT COMMONS - 1 LOWER	Hose100C	~	2018	2023		Y	
43	1	HL DGL-001 STUDENT COMMONS - 1 UPPER	10/ABC	93366389	2018	2030	2024	Y	RECOMMEND 2D SIGN
44	1	HL DGL-001 STUDENT COMMONS - 1 UPPER	Hose100C	~	2018	2023		Y	
45	1	Adj event centre 170 entrance	10/ABC	93367113	2018	2030	2024	Y	RECOMMEND 2D SIGN
46	1	Adj event centre 170 entrance	Hose100C	~	2018	2023		Y	
47	1	Adj office of register	10/ABC	93366532	2018	2030	2024	Y	RECOMMEND 2D SIGN
48	1	Adj office of register	Hose100C	~	2018	2023		Y	
49	1	Exam Centre NW D170	5/ABC	93366248	2018	2030	2024	Y	RECOMMEND 2D SIGN
50	1	Exam Centre NW D170	Hose100C	~	2018	2023		Y	
51	1	Exam Centre NE D170	10/ABC	93366385	2018	2030	2024	Y	RECOMMEND 2D SIGN
52	1	Exam Centre NE D170	Hose100C	~	2018	2023		Y	
53	1	Exam Centre SE D170	10/ABC	93366868	2018	2030	2024	Y	RECOMMEND 2D SIGN
54	1	Exam Centre SE D170	Hose100C	~	2018	2023		Y	
55	1	Exam Centre SW D170	10/ABC	93366365	2018	2030	2024	Y	RECOMMEND 2D SIGN
56	1	Exam Centre SW D170	Hose100C	~	2018	2023		Y	
57	1	Janitors Closet D174	10/ABC	93366251	2018	2030	2024	Y	
58	1	Student Commons Level 01 o/s Stair and Elev 11	5/CO2	93366246	2018	2030	2024	Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
59	1	Elevator Lobby 1st Level	10/ABC	93366386	2018	2030	2024	Y	RECOMMEND 2D SIGN
60	1	Elevator Lobby 1st Level	Hose100C	~	2018	2023		Y	
61	2	o/s Stair A-L02	10/ABC	93367115	2018	2030	2024	Y	RECOMMEND 2D SIGN
62	2	o/s Stair A-L02	Hose100C	~	2018	2023		Y	
63	2	Comms 213	15/CO2	77097968	2018	2023		Y	
64	2	Electrical 203	15/CO2	77097965	2018	2023		Y	
65	2	Elevator Lobby 2nd Level	10/ABC	93366864	2018	2030	2024	Y	RECOMMEND 2D SIGN
66	2	Elevator Lobby 2nd Level	Hose100C	~	2018	2023		Y	
67	2	HL D231 - JANITOR CLOSET	5/ABC	98578246	2020	2032	2026	Y	
68	2	o/s Stair B-L02	10/ABC	93366869	2018	2030	2024	Y	RECOMMEND 2D SIGN
69	2	o/s Stair B-L02	Hose100C	~	2018	2023		Y	
70	2	HL D280K - CORRIDOR	10/ABC	93366533	2018	2030	2024	Y	RECOMMEND 2D SIGN
71	2	HL D280K - CORRIDOR	Hose100C	~	2018	2023		Y	
72	2	HL D280 Workstations Hub o/s Stair E	10/ABC	93367112	2018	2030	2024	Y	RECOMMEND 2D SIGN
73	2	HL D280 Workstations Hub o/s Stair E	Hose100C	~	2018	2023		Y	
74	3	o/s Stair A-L03	10/ABC	93366536	2018	2030	2024	Y	RECOMMEND 2D SIGN
75	3	o/s Stair A-L03	Hose100C	~	2018	2023		Y	
76	3	HL D323 - COMMS	10/CO2	77097973	2018	2023		Y	
77	3	HL D301 - ELECTRICAL ROOM	10/CO2	77097980	2018	2023		Y	
78	3	3rd Level Elevator Lobby	10/ABC	93366252	2018	2030	2024	Y	RECOMMEND 2D SIGN
79	3	3rd Level Elevator Lobby	Hose100C	~	2018	2023		Y	
80	3	HL D331 - JANITOR CLOSET	10/ABC	93366866	2018	2030	2024	Y	
81	3	o/s Stair B-L03	10/ABC	93366245	2018	2030	2024	Y	RECOMMEND 2D SIGN
82	3	o/s Stair B-L03	Hose100C	~	2018	2023		Y	
83	4	o/s Stair A-L04	10/ABC	93366255	2018	2030	2024	Y	RECOMMEND 2D SIGN
84	4	o/s Stair A-L04	Hose100C	~	2018	2023		Y	
85	4	Adj 482	10/ABC	93366531	2018	2030	2024	Y	RECOMMEND 2D SIGN
86	4	Adj 482	Hose100C	~	2018	2023		Y	
87	4	HL D447 - COMMS	15/CO2	77097975	2018	2023		Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
88	4	HL D411 - SECURITY ROOM	15/CO2	77097969	2018	2023		Y	
89	4	O/S HL D408KB Charles W. Brown Lounge	10/ABC	93366390	2018	2030	2024	Y	RECOMMEND 2D SIGN
90	4	O/S HL D408KB Charles W. Brown Lounge	Hose100C	~	2018	2023		Y	
91	4	HL D468KA - CORRIDOR	10/ABC	93367109	2018	2030	2024	Y	RECOMMEND 2D SIGN
92	4	HL D468KA - CORRIDOR	Hose100C	~	2018	2023		Y	
93	4	HL D405 - ELECTRICAL ROOM	15/CO2	77097978	2018	2023		Y	
94	4	HL D477 - JANITOR CLOSET	10/ABC	93366250	2018	2030	2024	Y	
95	5	o/s Stair A-L05	10/ABC	93366863	2018	2030	2024	Y	RECOMMEND 2D SIGN
96	5	o/s Stair A-L05	Hose100C	~	2018	2023		Y	
97	5	HL D516 - LOUNGE/KIT	5/CO2	21009812	2019	2023		Y	
98	5	HL D543 - COMMS	15/CO2	77097966	2018	2023		Y	
99	5	HL D503 - ELECTRICAL ROOM	15/CO2	77097971	2018	2023		Y	
100	5	5th Level Elevator Lobby	10/ABC	93367111	2018	2030	2024	Y	RECOMMEND 2D SIGN
101	5	5th Level Elevator Lobby	Hose100C	~	2018	2023		Y	
102	5	By 584	10/ABC	93367116	2018	2030	2024	Y	RECOMMEND 2D SIGN
103	5	By 584	Hose100C	~	2018	2023		Y	
104	5	HL D553 - JANITOR CLOSET	10/ABC	93366388	2018	2030	2024	Y	
105	5	o/s Stair B-L05	10/ABC	93366258	2018	2030	2024	Y	RECOMMEND 2D SIGN
106	5	o/s Stair B-L05	Hose100C	~	2018	2023		Y	
107	PH	PH 001VB Penthouse Mechanical Area o/s Stair A L06	10/ABC	93367110	2018	2030	2024	Y	RECOMMEND 2D SIGN
108	PH	PH 001VB Penthouse Mechanical Area o/s Stair A L06	Hose100C	~	2018	2023		Y	
109	PH	PH 001 Penthouse Mechanical Area o/s Stair B L06	10/ABC	93366244	2018	2030	2024	Y	
110	PH	PH 001 Penthouse Mechanical Area o/s Stair B L06	Hose100C	~	2018	2023		Y	
111	PH	Mech penthouse elevator lobby	10/ABC	93367118	2018	2030	2024	Y	
112	PH	MECH PENTHOUSE	10 ABC	93366249	2018	2030	2024	Y	

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR = 1

Building Name	Site Address	City
BLADEN WING	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 19, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	2	Northeast Inside Room BV246 ELET RM	5/CO2	37510914	2017	2022		Y	
3	2	Northeast Outside Room BV246	5/ABC	21280792	2021	2033	2027	Y	
2	2	Northeast Outside Room BV246	Hose100C	~	2021	2026		Y	
4	2	Northeastoutside Room BV264	5/ABC	7123262	1986			Y	
5	2	Northeastoutside Room BV264	Hose100C	~	2021			Y	
6	2	South Outside Room B203, by Tim Hortons	10/abc	710636	2004	2028	2022	Y	
7	2	South Outside Room B203, by Tim Hortons	Hose100C	~	2021			Y	
8	2	Custodial Room B252	5/ABC	21280828	2021	2033	2027	Y	
11	2	Southwest Outside Room B2222	5/ABC	143765	2006	2030	2024	Y	
12	2	Southwest Outside Room B2222	Hose100C	~	2021	2026		Y	
13	2	West by Stair B2305	10/ABC	56207	2002			DUE	Y DUE TO 6 YEARS MAINT
14	2	West by Stair B2305	Hose100C	~	2021	2026		Y	
15	3	East in Room B346	5/ABC	15564074	2020	2032	2026	N	Exam
16	3	East in Room BV360(U)	5/ABC	316929	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
9	3	Southeast across from Gallery	5/ABC	56207	2000		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
10	3	Southeast across from Gallery	Hose100C	~	2021	2026		Y	
17	3	North in Room B337	10/ABC	709067	2004	2028	2022	Y	
18	3	North in Room B339	5/CO2	73510902	2017	2022		Y	
21	3	Outside bv326	5/ABC	21280850	2021	2033	2027	Y	
20	3	Outside bv326	Hose100C	~	2021	2026		Y	RECOMMEND 2D SIGN
22	3	Northeast Outside Room B342	10/ABC	710766	2004	2028	2022	Y	RECOMMEND 2D SIGN
23	3	Northeast Outside Room B342	Hose100C	~	2021	2026		Y	
19	3	Northeast in Room BV342	5/CO2	73510908	2017	2022		Y	
24	3	South in Center of Bookstore	5/ABC	9911	2001		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
25	3	South in Center of Bookstore	Hose100C	~	2021	2026		Y	
26	3	Southeast in Doris Gallery	5/ABC	673274	2012	2024	2030	Y	
27	3	Southeast in Room B368	5/CO2	73510903	2017	2022		Y	RECOMMEND 2D SIGN
28	3	Southeast Outside Room B368	5/ABC	21280826	2021	2033	2027	Y	
29	3	Southeast Outside Room B368	Hose100C	~	2021	2026		Y	
30	3	Southwest near Entrance to Bookstore BV303E	5/ABC	808577	1990		DUE	Y	DUE TO 6 YEARS MAINT
31	3	Southwest Outside Bookstore	5/ABC	21280817	2021	2033	2027	Y	RECOMMEND 2D SIGN
32	3	Southwest Outside Bookstore	Hose100C	~	2021	2026		Y	
33	4	East in Supression System Room	5/ABC	73097	2006	2030	2024	Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
34	4	East in Supression System Room	Hose100C	~	2020	2025		Y	
35	4	Northeast in Room BV450	5/CO2	73510909	2017	2022		Y	
36	4	Northeast in Room beside B445	5/CO2	73510916	2017	2022		Y	
39	4	Northwest in Room BV445	5/ABC	680814	2012	2024	2030	Y	
38	4	Northeast Outside Room BV450	5/ABC	143751	2006	2030	2024	Y	RECOMMEND 2D SIGN
37	4	Northeast Outside Room BV450	Hose100C	~	2021	2026		Y	
40	4	South in Room VF494	5/ABC	143754	2006	2030	2024	Y	
41	4	South in Room VF494	Hose100C	~	2021	2026		Y	
42	4	In BV481A (L -> B KEY)	5/ABC	7123263	-	-	-	Y	
43	4	Southeast Adj. Room BV482	5/ABC	893215	2009	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
44	4	Southeast Adj. Room BV482	Hose100C	~	2021	2026		Y	
45	4	Southeast in Electrical Room Adj. Room BV473	5/CO2	73510899	2017	2022		Y	
46	4	Southwest Outside Room BV400	10/ABC	194395	2004	2028	2022	Y	RECOMMEND 2D SIGN
47	4	Southwest Outside Room BV400	Hose100C	~	2021	2026		Y	
48	4	West Outside Room BV428	5/ABC	710902	2004	2028	2022	Y	RECOMMEND 2D SIGN
49	4	West Outside Room BV428	Hose100C	~	2021	2026		Y	
50	5	East in Room BV580	5/CO2	73510901	2017	2022		Y	
51	5	East Outside Room BV580	5/ABC	13269	1997	2033	2027	Y	RECOMMEND 2D SIGN
52	5	East Outside Room BV580	Hose100C	~	2021	2026		Y	
53	5	North in BV524	5/CO2	73510900	2017	2022		Y	
54	5	Northwest in Room BV525	5/ABC	839260	2010	2022	2028	Y	
55	5	Northeast in Room BV538	5/CO2	73510913	2017	2022		Y	
56	5	Northeast Outside Room BV538	5/ABC	143747	2006	2030	2024	Y	RECOMMEND 2D SIGN
57	5	Northeast Outside Room BV538	Hose100C	~	2021	2026		Y	
58	5	Southeast in Room BV587	5/ABC	898461	2005	2029	2023	Y	
59	5	Southeast Outside Room BV590	5/ABC	7123254				Y	OBSELETE - TOO OLD
60	5	Southwest in BV511(B)	5/ABC	73510910	2017	2029	2023	Y	*ROOM ON ROOF
61	5	Southwest Outside BV500	5/ABC	680847	2012	2024	2030	Y	RECOMMEND 2D SIGN
62	5	Southwest Outside BV500	Hose100C	~	2021	2026		Y	
63	5	West Outside BV526E	5/ABC	680834	2012	2024	2030	Y	RECOMMEND 2D SIGN
64	5	West Outside BV526E	Hose100C	~	2021	2026		Y	
65	R	Roof (SKD13) South in BV598 Key	10/ABC	97109	2008	DUE		Y	DUE TO H-TEST
66	R	Roof (SKD13) North in BV610 Key	10/ABC	971511	2008	DUE		Y	DUE TO H-TEST
67	R	Roof (SKD13) North In BV620	10/ABC	52861676	2021	2033	2027	Y	



FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR = 1

Building Name	Site Address	City
STUDENT CENTRE	1265 MILITARY TRAIL	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 18th and 19th, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
3	B	East in Kitchen	10/CO2	2826128	2009	2025		Y	RECOMMEND 2D SIGN
4	B	East Outside Room SL042 by Elevator	10/ABC	194392	2004	2028	2022	Y	RECOMMEND 2D SIGN
5	B	Southeast in Room SL032	10/CO2	329926	2009	2025		Y	
6	B	Southeast in Room SL033	10/CO2	11033582	2020	2025		Y	
7	B	Southeast in Room SL038 ELEV RM	10/BC	893099	2002	2031	2025	Y	
8	B	SL_021 East in Kitchen REX DEN	10/CO2	932380	2004	2025		Y	
9	B	SL-021 Kitchen Grill Area REX DEN	6I Kclass	49815468	2018	2023		Y	
10	B	SL-015 East behind bar REXDEN	10/ABC	194420	2004	2028	2022	Y	
11	B	West Outside Room SL003	10/ABC	194296	2004	2028	2022	Y	
12	1	East in Denistry on Campus	5/ABC	21280774	2021	2033	2027	Y	
13	1	Outside SL124 (SUBWAY)	10/CO2	11033585	2020	2025		Y	
14	1	Northeast Outside Room SL157	10/ABC	648672	2012	2024	2030	Y	RECOMMEND 2D SIGN
16	1	INSIDE SUBWAY	5/ABC	650713	2012		DUE	Y	DUE TO 6 YEEARS MAINT
18	1	Souteast in Campus Express Behind Cash	5/ABC	123697	1995			Y	
15	1	Southeast in Campus Express Back Room	5/ABC	512435	2010	2024	2030	Y	
19	1	Southeast in front of Asian Gourmet	10/ABC	194297	2004	2028	2022	Y	RECOMMEND 2D SIGN
17	1	Southeast Asian Gourmet Rear Kitchen	6I Kclass	3138365	2020	2025		Y	
20	1	Southeast in front of Hero Burger	10/ABC	196780	2003	2027	DUE	Y	DUE TO 6 YEEARS MAINT. RECOMMEND 2D
21	1	Southeast in Hero Burger Kitchen	6I Kclass	3138352	2020	2025		Y	REMOUNT REQUIRID
22	1	Southeast in KFC Kitchen	6I Kclass	3138368	2020	2025		Y	REMOUNT REQUIRID
23	1	Scsu	10/ABC	194400	2004	2028	2022	Y	RECOMMEND 2D SIGN

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
24	1	PITA LIFE	5/ABC	671678	2012	2024	DUE	Y	*New Tag Req'd
25	2	East in Room SL241 (ELEC RM)	10/CO2	11033581	2007	2022		Y	
26	2	East in SL270 Outside of SL250	10/ABC	194401	2004	2028	2022	Y	
27	2	Northeast Outside Room SL270	10/ABC	194289	2004	2028	2022	Y	RECOMMEND 2D SIGN
28	2	Northwest Outside Room SL218	10/ABC	673203	2012	2028	2024	Y	
29	2	Northwest Outside Room SL226A	10/ABC	194294	2004	2028	2022	Y	RECOMMEND 2D SIGN
30	2	Southeast Outside Room SL234	10/ABC	194431	2004	2028	2022	Y	RECOMMEND 2D SIGN
31	PH	Penthouse East via SL236 at Exit	10/CO2	11033579	2004	2025		Y	
33									
34									
35									
36									
37									
38									
39									
40									
41									
42									
43									
44									
45									

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR = 1

Building Name	Site Address	City
INSTRUCTIONAL CENTRE	1095 MILITARY TRAIL	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 20, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR N	MAY 2023 Inspections	REMARKS
1	B	West Outside Room IC40	5/ABC	271824	2011	2023	2029	Y	
2	B	West Outside Room IC40	Hose100C	~	2017	2022		Y	
3	B	Northeast Outside IC1	5/ABC	271789	2011	2023	2029	Y	
4	B	Northeast Outside IC1	Hose100C	~	2017	2022		Y	
6	B	Northwest Outside IC12	5/ABC	271787	2011	2023	2029	Y	
5	B	Northwest Outside IC12	Hose100C	~	2017	2022		Y	
7	B	Southwest In IC90 - Loading Dock	5/ABC	680856	2012	2024	2030	Y	
8	B	Southwest In IC90 - Loading Dock	Hose100C	~	2017	2022		Y	
9	B	Outside Women's Change Room IC19	5/ABC	271822	2011	2023	2029	Y	
10	B	Outside Women's Change Room IC19	Hose100C	~	2017	2022		Y	
11	B	IC130 - LECTURE HALL	5/ABC	271823	2011	2023	2029	N	
12	B	IC130 - LECTURE HALL	Hose100C	~	2010	DUE		N	
13	1	Center Outside Room IC130	5/ABC	271791	2011	2023	2029	Y	
14	1	Center Outside Room IC130	Hose100C	~	2017	2022		Y	
15	1	Northeast by elevator in LA PREP kitchen	5/ABC	226225	2011	2023	2029	Y	
16	1	Northeast by elevator in LA PREP kitchen	Hose100C	~	2017	2022		Y	
17	1	Northeast Outside Room IC101	5/ABC	271770	2011	2023	2029	Y	
18	1	Northeast Outside Room IC101	Hose100C	~	2017	2022		Y	
19	1	Northeast Outside The Hub	5/ABC	271839	2011	2023	2029	Y	
20	1	Northeast Outside The Hub	Hose100C	~	2017	2022		Y	
21	1	South Outside IC160	5/ABC	271809	2011	2023	2029	Y	
22	1	South Outside IC160	Hose100C	~	2017	2022		Y	
23	1	South Outside IC186	5/ABC	271825	2011	2023	2029	Y	
24	1	South Outside IC186	Hose100C	~	2017	2022		Y	
25	1	West by Vending Machine	5/ABC	271805	2011	2023	2029	Y	
26	1	West by Vending Machine	Hose100C	~	2017	2022		Y	
27	2	Center Adj. IC230	5/ABC	271816	2011	2023	2029	Y	
28	2	Center Adj. IC230	Hose100C	~	2017	2022		Y	
29	2	Center Adj. IC237	5/ABC	271838	2011	2023	2029	Y	
30	2	Center Adj. IC237	Hose100C	~	2017	2022		Y	
31	2	Northeast Outside Room IC200	5/ABC	271771	2011	2023	2029	Y	
32	2	Northeast Outside Room IC200	Hose100C	~	2017	2022		Y	
33	2	Northwest Outside Room IC212	5/ABC	271772	2011	2023	2029	Y	
34	2	Northwest Outside Room IC212	Hose100C	~	2017	2022		Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
35	2	South Outside Room IC262	5/ABC	271806	2011	2023	2029	Y	
36	2	South Outside Room IC262	Hose100C	~	2017	2022		Y	
37	2	Southwest Outside Room IC286	5/ABC	271819	2011	2023	2029	Y	
38	2	Southwest Outside Room IC286	Hose100C	~	2017	2022		Y	
39	2	West Outside Room IC220	5/ABC	271837	2011	2023	2029	Y	
40	2	West Outside Room IC220	Hose100C	~	2017	2022		Y	
41	3	Center Outside Room IC334	5/ABC	271801	2011	2023	2029	Y	
42	3	Center Outside Room IC334	Hose100C	~	2017	2022		Y	
43	3	Centre outside IC337	5/ABC	918382	2005	2029	2023	Y	
44	3	Centre outside IC337	Hose100C	~	2017	2022		Y	
45	3	Northeast Outside Room IC302	5/ABC	271827	2011	2023	2029	Y	
46	3	Northeast Outside Room IC302	Hose100C	~	2017	2022		Y	
47	3	Northeast Outside Room IC312	5/ABC	271836	2011	2023	2029	Y	
48	3	Northeast Outside Room IC312	Hose100C	~	2017	2022		Y	
49	3	South Outside Room IC362	5/ABC	271788	2011	2023	2029	Y	
50	3	South Outside Room IC362	Hose100C	~	2017	2022		Y	
51	3	Southwest Outside Room IC386	5/ABC	271803	2011	2023	2029	Y	
52	3	Southwest Outside Room IC386	Hose100C	~	2017	2022		Y	
53	3	West Outside Room IC325	5/ABC	271820	2011	2023	2029	Y	
54	3	West Outside Room IC325	Hose100C	~	2017	2022		Y	
55	4	Center Outside Room IC430	5/ABC	271821	2011	2023	2029	Y	
56	4	Center Outside Room IC430	Hose100C	~	2017	2022		Y	
57	4	Center Outside Room IC437	5/ABC	271815	2011	2023	2029	Y	
58	4	Center Outside Room IC437	Hose100C	~	2017	2022		Y	
59	4	Northeast Outside Room IC400A	5/ABC	271807	2011	2023	2029	Y	
60	4	Northeast Outside Room IC400A	Hose100C	~	2017	2022		Y	
61	4	Northwest Outside Room IC410	5/ABC	21280829	2021	2033	2027	Y	
62	4	Northwest Outside Room IC410	Hose100C	~	2017	2022		Y	
63	4	South Outside Room IC462	5/ABC	271840	2011	2023	2029	Y	
64	4	South Outside Room IC462	Hose100C	~	2017	2022		Y	
65	4	Southwest Outside Room IC485	5/ABC	271802	2011	2023	2029	Y	
66	4	Southwest Outside Room IC485	Hose100C	~	2017	2022		Y	
67	4	West Outside Room Women's Washroom	5/ABC	271834	2011	2023	2029	Y	
68	4	West Outside Room Women's Washroom	Hose100C	~	2017	2022		Y	
70									
71									

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR =

2

Building Name		Site Address		City	
ENVIRONMENTAL SCIENCE & CHEMISTRY BUILDING		1065 MILITARY TRAIL		SCARBOROUGH, ON	
Date of Inspection			Job / Ticket Number		Technician
October 20, 2023			UTSC - Campus Safety Inspection		UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	B	Northeast Adj. Stair B	5/ABC	41563	2021	2033	2027	Y	
2	B	Northeast Adj. Stair B	Hose100C	~	2019	2024		Y	
3	B	Elevator RM: 013 Communications	5/ABC	21280780	2021	2033	2027	Y	
4	B	Elevator RM: 013 Communications	Hose100C		2019	2024		Y	
5	B	Southeast Outside 005A	5/ABC	21280784	2021	2033	2027	Y	
6	B	Southeast Outside 005A	Hose100C	~	2015	DUE		Y	DUE TO H-TEST
7	B	Southwest By Stair C	5/ABC	21280852	2021	2033	2027	Y	
8	B	Southwest By Stair C	Hose100C	~	2019	2024		Y	
9	1	South Research Lab Support	5/ABC	21280781	2021	2033	2027	Y	
10	1	South Research Lab Support	Hose100C	~	2019	2024		Y	
11	1	Southeast In Room 112	5/ABC	21280786	2021	2033	2027	Y	RECOMMEND 2D SIGN
12	1	Southeast In Room 114	5/ABC	66738796	2016	2028	2022	Y	RECOMMEND 2D SIGN
13	1	Southeast In Room 113	5/ABC	66737942	2016	2028	2022	Y	RECOMMEND 2D SIGN
14	1	Southeast Research Lab Support	5/ABC	21280789	2021	2033	2027	Y	RECOMMEND 2D SIGN
15	1	Southeast Research Lab Support	Hose100C	~	2019	2024		Y	
16	1	S/e lab room 120	10/ABC	93366534	2010	2022	2028	Y	RECOMMEND 2D SIGN
17	1	South In Room 122	5/ABC	66737979	2016	2028	2022	Y	RECOMMEND 2D SIGN
18	1	Southwest In Room 123	5/ABC	66733538	2016	2028	2022	Y	RECOMMEND 2D SIGN
19	1	Southwest In Room 124	5/ABC	66738797	2016	2028	2022	Y	RECOMMEND 2D SIGN
20	1	Southwest Research Lab Support	5/ABC	21280827	2021	2033	2027	Y	
21	1	Southwest Research Lab Support	Hose100C	~	2019	2024		Y	
23	2	By Stair B	5/ABC	21280880	2021	2033	2027	Y	
22	2	By stair B	Hose100C	~	2019	2024		Y	
24	2	By Stair A	5/ABC	21280813	2021	2033	2027	Y	
25	2	By stair A	Hose100C	~	2019	2024		Y	
26	2	Southeast In Room 216	5/ABC	66738798	2016	2028	2022	Y	RECOMMEND 2D SIGN
27	2	Southwest In Room 222	5/ABC	66738774	2016	2028	2022	N	*CLASS
28	2	Southwest In Room 224	5/ABC	66733544	2016	2028	2022	N	*CLASS
29	2	Southwest In Room 226	5/ABC	66733539	2016	2028	2022	Y	RECOMMEND 2D SIGN
30	2	Southwest Research Lab Support	5/ABC	21280833	2021	2033	2027	Y	
31	2	Southwest Research Lab Support	Hose100C	~	2019	2024		Y	
32	3	Centre Outside Room 315	5/ABC	66737955	2016	2028	2022	Y	
33	3	Northeast By Stair B	5/ABC	21280886	2021	2033	2027	Y	
34	3	Northeast By Stair B	Hose100C	~	2019	2024		Y	
35	3	Southeast By Stair A	5/ABC	21280772	2021	2033	2027	Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
36	3	Southeast By Stair A	Hose100C	~	2019	2024		Y	
37	3	Southeast In Room 306	5/ABC	66737978	2016	2028	2022	Y	RECOMMEND 2D SIGN
38	3	Southeast In Room 306A	5/ABC	66738768	2016	2028	2022	Y	RECOMMEND 2D SIGN
39	3	Southeast In Room 313	5/ABC	66733545	2016	2028	2022	Y	RECOMMEND 2D SIGN
40	3	Southeast Research Lab Support	5/ABC	21280831	2021	2033	2027	Y	
41	3	Southeast Research Lab Support	Hose100C	~	2019	2024		Y	
42	4	Center Adj. Room 414	5/ABC	66737983	2016	2028	2022	Y	RECOMMEND 2D SIGN
43	4	Center In Room 411	5/ABC	66733540	2016	2028	2022	Y	
44	4	Northeast By stair B	5/ABC	21280793	2021	2033	2027	Y	
45	4	Northeast By stair B	Hose100C	~	2019	2024		Y	
46	4	Southeast In Room 409	5/ABC	66737952	2016	2028	2022	Y	RECOMMEND 2D SIGN
47	4	Southeast Research Lab Support by stair A	5/ABC	21280837	2021	2033	2027	Y	
48	4	Southeast Research Lab Support by stair A	Hose100C	~	2019	2024		Y	
49	4	Southwest In Room 423	5/ABC	66737967	2016	2028	2022	Y	RECOMMEND 2D SIGN
50	4	Southwest In Room 427	5/ABC	66733542	2016	2028	2022	Y	RECOMMEND 2D SIGN
51	4	Southwest Research Lab Support by stair C	5/ABC	21280804	2021	2033	2027	Y	
52	4	Southwest Research Lab Support by stair C	Hose100C	~	2019	2024		Y	
53	5	Centre Outside Rear Elevator	10/ABC	32149055	2017	2029	2023	Y	RECOMMEND 2D SIGN
54	5	Northeast By Stair A	5/ABC	21280796	2021	2033	2027	Y	
55	5	Northeast By Stair A	Hose100C	~	2019	2024		Y	
56	5	BY Stair B	5/ABC	21280819	2021	2033	2027	Y	
57	5	BY Stair B	Hose100C	~	2019	2024		Y	
58	5	Southeast In 506 - South Door	5/ABC	66737956	2016	2028	2022	Y	RECOMMEND 2D SIGN
59	5	Southeast Outside Room 516	5/ABC	66737946	2016	2028	2022	Y	
60	5	Southeast Outside Room 518	5/ABC	66737985	2016	2028	2022	Y	
61	5	Southwest Inside Research Lab Support	5/ABC	21280840	2021	2033	2027	Y	
62	5	Southwest Inside Research Lab Support	Hose100C	~	2019	2024		Y	
63	5	Southwest In Room 522	5/ABC	66737951	2016	2028	2022	Y	RECOMMEND 2D SIGN
64	6	Centre elevator	10/ABC	648861	2012	2024	2030	Y	RECOMMEND 2D SIGN
65	6	East By 610C	20/ABC	919949	2015		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
66	6	East By East Exit stair A	5/ABC	21280844	2021	2033	2027	Y	
67	6	East By East Exit stair A	Hose100C	~	2019	2024		Y	
68	6	East By West Exit Stair C	5/ABC	21280843	2021	2033	2027	Y	
69	6	East By West Exit Stair C	Hose100C	~	2019	2024		Y	
70	6	Adjacent to Elevator Adj 610A	10/ABC	52861653	2021	2033	2027	Y	

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

IPR = 7

Building Name	Site Address	City
SCIENCE WING	1265 Military Trail	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Technician
October 26 and October 27 and October 30, 2023	UTSC - Campus Safety Inspection	UTSC - Sudev Suresh

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	RMP	1ST LOADING DOCK BOTTOM OF RAMP	5/ABC	21280832	2021	2033	2027	Y	
2	RMP	1ST LOADING DOCK BOTTOM OF RAMP	HOSE 100C		2010	DUE		Y	DUE TO H-TEST
3	LIFT	1ST LOADING DOCK FORK LIFT #15	5/ABC	21280835	2021	2033	2027	Y	
4	RMP	1ST LOADING DOCK NORTHEAST TOP OF RAMP	5/ABC	199940	2002	2026	2032	Y	
5	RMP	1ST LOADING DOCK NORTHEAST TOP OF RAMP	HOSE 100C		LOANER	DUE		Y	REQUIRE REPLACEMENT TO NEW HOSE
6	RMP	1ST LOADING DOCK SOUTH AT THE ENT TO SW BLDG S114	5/ABC	144250	2006	2030	2024	Y	
7	RMP	1ST LOADING DOCK WEST ADJ AA BLDG ELEV BY STAIR	5/ABC	52861657	2021	2033	2027	Y	
8	RMP	1ST LOADING DOCK WEST ADJ AA BLDG ELEV BY STAIR	HOSE 100C		2010	DUE		Y	DUE TO H-TEST
9	CART	FMD - Facility Cart 1	5/ABC	21280787	2021	2033	2027	Y	
10	CART	FMD - Facility Cart 2	10/ABC	52861658		2033	2027	Y	
11	1	North Outside Room SW102	5/ABC	316734	2008	DUE		Y	DUE TO H-TEST
12	1	North Outside Room SW102	Hose100C	~	2021	2026		Y	
13	1	North in Room SW103 Southwest Pillar Adj. Stair to Mezz	10/ABC	710773	2004	2028	2022	Y	RECOMMEND 2D SIGN
14	1	Sw 103 B	5/ABC	839265	2010	2022	2028	Y	RECOMMEND 2D SIGN
15	1	SW 103 C - Elevator #5 Room (H-Wing to 5th Floor)	5/CO2	300520	2014	2024		Y	RECOMMEND 2D SIGN
16	1	OUTSIDE Sw 103 E	10/ABC	91676602	2015		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
17	1	OUTSIDE Sw 103 E	Hose100C	~	2021	2026		Y	
18	1	sw 103 H	5/ABC	808801	1989			Y	OBSOLETE - TOO OLD. RECOMMEND 2D
19	1	OUTSIDE Sw 103S	5/ABC	496369	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
20	1	Sw 103 J	10/ABC	34243994	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
21	1	SW 103N	5/ABC	39253789	2012		DUE	Y	DUE TO 6 YEARS MAINT. REMOUNT REQ.
22	1	SW 103 M	10/ABC	648849	2012	2024	2030	Y	RECOMMEND 2D SIGN
23	1	SW 103J (Power-House Control Room)	10/ABC	380794	2002		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
24	1	FHC sw103F	5/ABC	144251	2006	2030	2024	Y	
25	1	FHC SW 103F	Hose100C	~	2021	2026		Y	
26	1	OUTSIDE S103R	10/ABC	52861656	2021	2033	2027	Y	RECOMMEND 2D SIGN
27	1	SW 103 L (Electrical Room)	10/CO2	11033590	2020	2032	2026	Y	RECOMMEND 2D SIGN
28	1	SW 103 P Elevators 8 & 9 (B-Wing Passenger by Tim Horton and B-Wing Freight by Book Store)	5/CO2	73510920	2017	2029	2023	Y	
29	1	SW 105 CARPENTRY	10/ABC	97109	2000	2024	2030	Y	
30	1	SW 109B	10/ABC	58261669	2021	2033	2027	Y	RECOMMEND 2D SIGN
31	1	Sw 109 workshop	10/ABC	91676580	2015		DUE	Y	DUE TO 6 YEARS MAINT.
32	1	Sw 109B	5/ABC	121045	1991		DUE	Y	DUE TO 6 YEARS MAINT.

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
33	1	North in Room SW109A via SW109	5/ABC	316932	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
34	1	North OUTSIDE Room SW109C via SW109D	10/ABC	2606938	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
35	1	North INSIDE Room SW109C via SW109D	10/ABC	316591	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
36	1	North in Room SW109D Outside SW109B	5/ABC	143762	2006	2030	2024	Y	
37	1	North in Room SW109D Outside SW109B	Hose100C	~	2021	2026		Y	
38	1	North Outside SW109 into SW-109 Fabrication Lab	5/ABC	2570	2003	DUE		Y	DUE TO H-TEST
39	1	North in Room SW111 via SW109D AA Key	10/BC	194399	2004	2028	2022	Y	
40	1	North in Room SW112A	5/ABC	21280803	2021	2033	2027	Y	
41	1	North in Room SW115 (Elevator Room)	5/CO2	11040234	2020	2032	2026	Y	
42	1	North in Room SW119	5/ABC	315252	2008	DUE		Y	DUE TO H-TEST
43	1	North in Room SW120	5/ABC	125230	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
44	1	North in Room SW121	5/ABC	39253788	2015		DUE		Construction
45	1	North in Room SW123	10/ABC	709180	2004	2022	2028		Construction
46	1	IN ROOM SW129 VIA SW128	10/ABC	710065	2010	2022	2028	N	Exam
47	1	CENTER IN ROOM SW 128	5/ABC	508373	2008	DUE		N	Exam
48	1	North Outside Room SW128	5/ABC	496366	2008	DUE		Y	DUE TO H-TEST
49	1	North Outside Room SW128	Hose100C	~	2021	2026		Y	
50	1	North in Room SW132	5/ABC	890053	2009	DUE		Y	
51	1	North in Room SW132	5/ABC	893217	2009	DUE		Y	
52	1	Center in Room SW133	5/CO2	538707	2020	2025		Y	RECOMMEND 2D SIGN
53	1	Center Outside Room SW133	10/ABC	470591	2009	DUE		Y	DUE TO H-TEST
54	1	Center Outside Room SW133	Hose100C	s	2021	2026		Y	
55	1	Center in Room SW134	5/ABC	7123263	2022			Y	OBSOLETE - TOO OLD. RECOMMEND 2D SIGN
56	1	Center in Room SW135	5/ABC	39253812	2015		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D SIGN
57	1	Center in Room SW135	5/ABC	41563	1998	2022	2028	Y	RECOMMEND 2D SIGN
58	1	Room SW138	10/ABC	648862	2012	2024	2030	Y	
59	1	South in Room SW141 via SW140V	5/ABC	39253787	2015		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D SIGN
60	1	SOUTH OUTSIDE ROOM SW143	5/ABC	316583	2008	DUE		Y	DUE TO H-TEST.
61	1	SOUTH OUTSIDE ROOM SW143	HOSE 100C	~	2021	2026		Y	
62	1	South in Room SW143	5/ABC	39253835	2015		DUE	N	Exam
63	1	South in Room SW144 via SW143	10/ABC	710651	2004	2028	2022	N	Exam
64	1	South in Room SW147	5/ABC	316110	2008	DUE		Y	DUE TO H-TEST
65	1	Room sw148	10/ABC	710892	2004	2028	2022	Y	RECOMMEND 2D SIGN
67	1	SOUTH OUTSIDE ROOM SW151	5/ABC	315251	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
68	1	SOUTH OUTSIDE ROOM SW151	HOSE 100C	~	2021	2026		Y	
69	1	South in Room SW151	5/CO2	11040236	2020	2025		Y	
70	1	South in Room SW153A	5/ABC	360836	2007	2031	2025	Y	RECOMMEND 2D SIGN
71	1	South in Room SW153A	5/CO2	678694	2014	2024		Y	RECOMMEND 2D SIGN

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
72	1	South in Room SW153B	5/ABC	55642	2002	2024	2032	Y	RECOMMEND 2D SIGN
73	1	South in Room SW153B	5/CO2	11040242	2020	2025		Y	RECOMMEND 2D SIGN
74	1	South in Room SW155	5/ABC	316101	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
75	1	South in Room SW159A	10/ABC	253530	2011	2023	2029	Y	RECOMMEND 2D SIGN
76	1	South in Room SW159B	5/CO2	11040231	2020	2025		Y	RECOMMEND 2D SIGN
77	1	South in Room SW159B	5/CO2	11040246	2020	2025		Y	RECOMMEND 2D SIGN
78	1	South in Room SW159B	5/ABC	610849	2008	DUE		Y	DUE TO H-TEST.
79	1	South in Room SW159A Storage Room	5/CO2	778076	2007	2025		Y	RECOMMEND 2D SIGN
80	1	South in Room SW161	10/ABC	74609710	2019	2031	2025	Y	RECOMMEND 2D SIGN
81	1	South in Room SW164	5/ABC	893231	2009	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
82	1	South Outside Room SW159B	10/ABC	58927	2003		DUE	Y	DUE TO 6 YEARS MAINT.
83	1	South Outside Room SW159B	Hose100C	~	2021	2026		Y	
84	1	South in Room SW166	5/ABC	316592	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
85	1	South in Room SW169	5/ABC	387936	1990	2029	2023	Y	
86	2	North in 205A	5/ABC	46764	2002		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
87	2	Rm 205 Power plant by main power	5/CO2	679953	2014	2024		N	*Blocked Off
88	2	In Room SW205A by FACP(SW103 mezz)	5/CO2	73510912	2017	2022		Y	
89	2	Room SW204 - Print Shop	5/ABC	839259	2010	2022	2028	Y	RECOMMEND 2D SIGN
90	2	North in Room SW204 by Rear Exit	10/ABC	275894	1999	2023	2029	Y	RECOMMEND 2D SIGN
91	2	North In Room SW204 by Night Riders	5/ABC	839261	2010	2022	2028	Y	RECOMMEND 2D SIGN
92	2	North in Room SW204 by Order Desk	5/ABC	839276	2010	2022	2028	Y	RECOMMEND 2D SIGN
93	2	North in Tunnel to AA Bldg. Adj. Sw204	5/CO2	41669555	2022			Y	OBSELETE - TOO OLD
94	2	North Outside Room SW204	5/ABC	143697	2006	2030	2024	Y	
95	2	North Outside Room SW204	Hose100C	~	2021	2026		Y	
96	2	North in Room SW208A	5/CO2	11040225	2020	2032	2026	Y	
97	2	North Outside Room SW208B	5/ABC	316108	2008	DUE		Y	DUE TO H-TEST
98	2	North Outside Room SW208B	Hose100C	~	2021	2026		Y	
100	2	North Outside Room SW216	5/ABC	39253801	2015		DUE	Y	DUE TO 6 YEARS MAINT.
101	2	North Outside Room SW216	Hose100C	~	2021	2026		Y	
102	2	Center in Room SW218	5/CO2	11040230	2020	2025		Y	
103	2	Center in Rom SW218A	5/ABC	212808842	2021	2033	2027	Y	
104	2	North in Room SW219	5/ABC	881887	1996	2032	2026	Y	
105	2	Center Outside Room SW221	5/ABC	316593	2008	DUE		Y	DUE TO H-TEST
106	2	Center Outside Room SW221	Hose100C	~	2021	2026		Y	
107	2	Center in Room SW222	5/ABC	96452	1995	2031	2025	Y	RECOMMEND 2D SIGN
108	2	Room225	10/ABC	710914	2004	2028	2022	Y	RECOMMEND 2D SIGN
109	2	Center in Room SW225A	10/ABC	359098	2010	2022	2028	Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
110	2	Center in Room SW225A	10/ABC	43036	2002	2028	2022	Y	RECOMMEND 2D SIGN
111	2	Center in SW226 - Transformer Room	5/CO2	11040382	2020	2025		N	KEY = ?
112	2	Center in Room SW227A	5/ABC	39253763	2015		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
113	2	Center in Room SW227A	5/CO2	11040224	2020	2025		Y	RECOMMEND 2D SIGN
114	2	Center Outside Room SW227	5/ABC	316114	2008	DUE		Y	DUE TO H-TEST
115	2	Center Outside Room SW227	Hose100C	~	2021	2026		Y	
116	2	Center in Room SW228	5/ABC	189418	2000	2024	2030	Y	RECOMMEND 2D SIGN
117	2	Center in Rom SW229A via SW229	5/ABC	510650	1999			Y	
118	2	Center in Room SW229A	5/ABC	890052	2009	DUE		Y	
119	2	Center in Room SW233	10/ABC	583023	2007	2031	2025	Y	RECOMMEND 2D SIGN
120	2	Center in rm SW233A Internal 2nd Level Control Room	10/ABC	710645	2004	2028	2022	Y	
121	2	South In Room SW234A via SW234	5/ABC	276175	2011	2023	2029	N	*Construction
122	2	South In Room SW234C via SW234	10/ABC	695527	2012	2024	2030	Y	***Relabelling***
123	2	South in Room SW234G	5/ABC	1205	2012	2024	2030	Y	RECOMMEND 2D SIGN
124	2	Outside Room SW235	5/ABC	39253797	2015		DUE	Y	DUE TO 6 YEARS MAINT.
125	2	Outside Room SW235	Hose100C	~	2021	2026		Y	
126	2	South in Room SW235A via SW235	5/CO2	11040229	2020	2025		Y	RECOMMEND 2D SIGN
127	2	South in Room SW236 via SW236A	5/ABC	21280800	2021	2033	2027	Y	No Access
128	2	South in Room SW237	5/ABC	437791	2006	2030	2024	Y	RECOMMEND 2D SIGN
129	2	South in Room SW237	5/ABC	750207	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
130	2	South in Room SW240	5/ABC	673222	2012			Y	RECOMMEND 2D SIGN
131	2	South in Room SW240	5/ABC	457521	2000			Y	RECOMMEND 2D SIGN
132	2	South in Room SW241	5/ABC	504622	2004			Y	RECOMMEND 2D SIGN
133	2	South in Room SW242	10/ABC	359131	2010				Missing
134	2	South in Room SW242	5/CO2	538707	2003				Missing
135	2	South in Room SW246	5/ABC	211280799	2021	2033	2027	Y	RECOMMEND 2D SIGN
136	2	South in Room SW247	5/ABC	839268	2010	2022	2028	Y	RECOMMEND 2D SIGN
137	2	South in Room SW248	5/ABC	446232	2002			Y	COULD NOT TESTED - UNDER CONS
138	2	South Outside Room SW248	10/ABC	68890	2003		DUE	Y	DUE TO 6 YEARS MAINT.
139	2	South Outside Room SW248	Hose100C	~	2021	2026		Y	
140	2	Sw 249	5/ABC	893226	2003			Y	COULD NOT TESTED - UNDER CONS
141	2	South in Room SW250 Prep Lab	5/ABC	893258	2009			Y	COULD NOT TESTED - UNDER CONS
142	2	South in Room SW251	5/CO2	73510171	2017	2029	2023	Y	
143	2	South in Room SW252	5/ABC	890064	2009	DUE			*Construction
144	2	South in Room SW253	5/ABC	893212	2009	DUE			*Construction
145	2	South Outside Room SW260	10/CO2	2870	2005	DUE		Y	DUE TO H-TEST
146	2	South Outside Room SW260	Hose100C	~	2021	2026		Y	
147	2	South in Room SW262	5/ABC	815222	2006	2030	2024	Y	RECOMMEND 2D SIGN
148	3	Northwest Adj. Elevator #1 by Main Entrance	10/ABC	710647	2004	2028	2022	Y	
149	3	Northwest Adj. Elevator #1 by Main Entrance	Hose100C	~	2021	2026		Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
150	3	Sw 302 - DCM	5/ABC	21280807	2021	2033	2027	Y	RECOMMEND 2D SIGN
151	3	Northeast in Room S303 by 303I	5/ABC	21280802	2021	2033	2027	Y	
152	3	Northeast Outside Room SW304, Police Office	5/ABC	39253812	2006	2032	2026	Y	
153	3	Northeast Outside Room SW304, Police Office	Hose100C	~	2021	2026		Y	
154	3	Northeast in Room SW304, Police Office by Reception	5/ABC	316919	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
155	3	Northeast in Room SW304, Police Office by Washroom	5/ABC	21280775	2021	2033	2027	Y	RECOMMEND 2D SIGN
156	3	North Outside Room SW308	5/ABC	316106	2008	DUE		Y	DUE TO H-TEST
157	3	North Outside Room SW308	Hose100C	~	2021	2026		Y	
158	3	Center in Room SW311	5/ABC	7123264	1989			Y	REMOUNT
159	3	Outside Room SW311	10/ABC	710649	2004	2028	2022	Y	
160	3	Outside Room SW311	Hose100C	~	2021	2026		Y	
161	3	Center in Room SW313	5/ABC	316729	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
162	3	In Room SW316	5/ABC	86345435	2017	2029	2023		*Missing
163	3	In SW317	5/ABC	435525	2006	DUE			*Missing
164	3	Center Outside Room SW319	5/ABC	316100	2008	DUE		Y	DUE TO H-TEST
165	3	Center Outside Room SW319	Hose100C	~	2021	2026		Y	
166	3	South in Room SW321	10/ABC	710558	2004	2022	2028	Y	
167	3	In Room SW321	10/CO2	1095	2003	2025		Y	
168	3	Outside Room SW321	5/ABC	144313	2006	2030	2024	Y	
169	3	Outside Room SW321	Hose100C	~	2021	2026		Y	
170	3	In Room SW322	10/CO2	327480	2005	2025			Construction
171	3	In Room SW323	5/CO2	73510612	2017	2022		Y	
172	3	South in Room SW326	5/ABC	262339	2015		DUE	Y	DUE TO 6 YEARS MAINT.
173	3	South in Room SW328	10/ABC	699569	2012		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D SIGN
174	3	South in Room SW330	5/ABC	7750	2003	2027	2033	Y	RECOMMEND 2D SIGN
175	3	South in Room SW331	5/ABC	839257	2010	2022	2038	Y	RECOMMEND 2D SIGN
176	3	South in Room SW332	5/ABC	839267	2010	2022	2028	Y	RECOMMEND 2D SIGN
177	3	South Outside Room SQ330,331,332	5/ABC	44721	2003	2029	2023	Y	
178	3	South Outside Room SQ330,331,332	Hose100C	~	2021	2026		Y	
179	4	Outside Room SW404	5/ABC	21280767	2021	2033	2027	Y	
180	4	Outside Room SW404	Hose100C	~	2021	2026		Y	
181	4	Northeast Outside Room SW410	5/ABC	316918	2008	DUE		Y	DUE TO H-TEST
182	4	Northeast Outside Room SW410	Hose100C	~	2021	2026		Y	
183	4	Northwest Outside Room SW418	5/ABC	756239	2003		DUE	Y	DUE TO 6 YEARS MAINT.
184	4	Northwest Outside Room SW418	Hose100C	~	2021	2026		Y	
185	4	In Room SW421A	5/ABC	893220	2009	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
186	4	North Outside Room SW421	5/ABC	316590	2008	DUE		Y	DUE TO H-TEST
187	4	North Outside Room SW421	Hose100C	~	2021	2026		Y	
188	4	Sw 422	10/ABC	710906	2004	2028	2022	Y	
189	4	Center Outside Room SW422	5/ABC	500272	2008	DUE		Y	DUE TO H-TEST
190	4	Center Outside Room SW422	Hose100C	~	2021	2026		Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
191	4	Center in Room SW423	10/CO2	1103588	2020	2025		Y	RECOMMEND 2D SIGN
192	4	front of lab Room SW426	5/ABC	675199	2012	2024	2030	Y	RECOMMEND 2D SIGN
193	4	back of lab SW426	5/ABC	893216	2009	DUE		Y	DUE TO H-TEST
194	4	Center in Room SW427	10/CO2	1103584	2020	2025		Y	RECOMMEND 2D SIGN
195	4	Center Outside Room SW427A	5/ABC	316594	2008	DUE		Y	DUE TO H-TEST
196	4	Center Outside Room SW427A	Hose100C	~	2021	2026		Y	
197	4	South Outside Room SW428	5/ABC	143572	2006	2030	2024	Y	
198	4	South Outside Room SW428	Hose100C	~	2021	2026		Y	
199	4	In Room SW428	10/CO2	517883	2010	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
200	4	South in Room SW429	10/CO2	436834	2010	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
201	4	In Room SW432	5/ABC	675197	2012	2024	2030	Y	RECOMMEND 2D SIGN
202	4	In Room SW432	5/CO2	302986	2003	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
203	4	South in Room SW433	5/ABC	675178	2012	2024	2030	Y	RECOMMEND 2D SIGN
204	4	In Room SW435	5/CO2	73510157	2017	2022		Y	
205	4	South Outside Room SW435	5/ABC	143761	2006	2030	2024	Y	
206	4	South Outside Room SW435	Hose100C	~	2021	2026		Y	
207	4	Soutwest in Hall Beside SW442	10/CO2	11033578	2020	2025		Y	
208	4	Soutwest in Hall Beside SW442	Hose100C	~	2021	2026		Y	
209	4	Drama Dept. SW444 LL Brown Theatre Catwalk at Stairwell by SW442	5/CO2	11040226	2020	2025		Y	
210	4	Outside Room SW442 between SW & SY	5/ABC	500291	2008	DUE		Y	DUE TO H-TEST. RECOMMEND 2D SIGN
211	5	By restroom elevator lobby 502	5/ABC	44733	2003		DUE	Y	DUE TO 6 YEARS MAINT.
212	5	By restroom elevator lobby 502	Hose100C	~	2021	2026		Y	
213	5	Outside sw503C	5/ABC	1988647	2002		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D SIGN
214	5	Northeast Outside Room SW503G	5/ABC	893209	2009	DUE		Y	OPPOSITE 505C
215	5	Northeast Outside Room SW503G	Hose100C	~	2021	2026		Y	OPPOSITE 505C
216	5	Northwest Outside Room SW504C	5/ABC	916288	2004	2028	2022	Y	
217	5	Northwest Outside Room SW504C	Hose100C	~	2021	2026		Y	
218	5	Northeast Outside Room SW505C	5/CO2	4169567	1984			Y	OBSOLETE - TOO OLD. RECOMMEND 2D DUE TO H-TEST.
219	5	Northeast Outside Room SW507B	5/ABC	893214	2009	DUE		Y	RECOMMEND 2D SIGN
220	5	North in Room SW512	5/ABC	257621	1998		DUE	Y	DUE TO 6 YEARS MAINT.
221	5	North Outside Room SW512	5/ABC	893225	2009	DUE		Y	DUE TO H-TEST
222	5	North Outside Room SW512	Hose100C	~	2021	2026		Y	
223	5	Northin Room SW514	5/ABC	31347	1994	2030	2024	Y	RECOMMEND 2D SIGN
224	5	North Outside Room SW521B	10/ABC	52861672	2021	2033	2027	Y	
225	5	North Outside Room SW521B	Hose100C	~	2021	2026		Y	
226	5	Center in Room SW527	5/CO2	11040227	2020	2025			*CONSTRUCTION
227	5	Center Outside Room SW527	10/CO2	11033575	2020	2025		Y	RECOMMEND 2D SIGN
228	5	Center in Room SW529	5/ABC	21280801	2021	2033	2027	Y	RECOMMEND 2D SIGN
229	5	Center in Room SW536	10/ABC	709436	2004	2028	2022	Y	
230	5	Center Outside Room SW536	5/ABC	107924	2005	2029	2023	Y	
231	5	Center Outside Room SW536	Hose100C	~	2021	2026		Y	

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
232	5	Center in Room SW538	10/ABC	91700957	2015		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
233	5	South in Room SW544	10/ABC	710087	2004	2028	2022	Y	RECOMMEND 2D SIGN
234	5	South Outside Room SW544	5/ABC	706096	1997	DUE		Y	DUE TO H-TEST
235	5	South Outside Room SW544	Hose100C	~	2021	2026		Y	
236	5	South in Room SW546	5/ABC	839266	2010	2022	2028	Y	RECOMMEND 2D SIGN
237	5	South in Room SW553	5/ABC	808558	1990		DUE	Y	DUE TO 6 YEARS MAINT. RECOMMEND 2D
238	5	South Outside Room SW555	10/ABC	710762	2004	2028	2022	Y	RECOMMEND 2D SIGN
239	5	South Outside Room SW561	5/ABC	7123256	2022			Y	OBSOLETE - TOO OLD
240	5	South Outside Room SW561	Hose100C	~	2021	2026		Y	
241	6	East in Room SW611 Mechanical Room, on Unit Adj. Exit SW612A BY AC-17	10/ABC	52861652	2021	2033	2027	Y	REMOUNT
242	6	North in Room SW611 Mechanical Room at Exit BY RF 16	10/ABC	52864743	2021	2033	2027	Y	REMOUNT
243	6	South in Room SW611 Mechanical Room, at Exit SW612	10/CO2	11033583	2020	2025		Y	REMOUNT
244	6	West in SW611 MechanicalRoom Pillar by AC16	10/CO2	11033589	2020	2025		Y	REMOUNT
245	6	West in SW611 MechanicalRoom Pillar by Exit SW612A	10/CO2	11033580	2020	2025		Y	REMOUNT
246	6	South in Room SW611 Mechanical Room, at Exit SW612B	10/ABC	52857643	2021	2033	2027	Y	REMOUNT
247	6	Northwest in SW624	5/ABC	839256	2010	2022	2028	Y	
248	6	Northwest by Room SW624A	10/ABC	52861673	2021	2033	2027	Y	RECOMMEND 2D SIGN
249	6	Northwest by Room SW624A	Hose100C	~	2021	2026		Y	RECOMMEND 2D SIGN
250	6	Northwest Outside Room SW624	5/CO2	73510501	2017	2022		Y	
251	6	North Outside Room SW625	5/ABC	987098	1996	2032	2026	Y	RECOMMEND 2D SIGN
252	6	Northeast Outside Room SW636	5/ABC	893218	2009	DUE		Y	DUE TO H-TEST
253	6	Northeast Outside Room SW636	Hose100C	~	2021	2026		Y	
254	6	Northwest Outside Room SW670 Vivarium	5/ABC	5066	1996	DUE		Y	DUE TO H-TEST
255	6	Northwest Outside Room SW670 Vivarium	Hose100C	~	2021	2026		Y	
256	6	680 692 Area South Vivarium Foyer	10/ABC	710038	2004	2028	2022	Y	
257	6	680 692 Area South Vivarium Foyer	Hose100C	~	2021	2026		Y	
258	7	Northeast in Room 702A	5/CO2	73510919	2017	2023		Y	
259	7	Northeast in Room SW706	5/CO2	73510906	2017	2023		Y	RECOMMEND 2D SIGN
260	7	SW713 - VIVARIUM LAB	5/ABC	490455	2010		DUE	N	lab
261	7	SW713 - VIVARIUM LAB	HOSE 100C	~	2013	DUE		N	lab

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

Building Name	Site Address	City
DAYCARE	1255 MILITARY TRAIL	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Lead Technician
October 25, 2023	UTSC - Campus Safety Inspection	UTSC - Byron Wilson

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	G	EAST IN DINING ROOM	5/ABC	839280	2010	2022	2028	Y	Daycar
2	G	North in Kitchen	5/ABC	839270	2010	2022	2028	Y	
3	G	North Outside Kitchen	5/ABC	839253	2010	2022	2028	Y	
4	G	Northwest in Mechanical/ Observation Room	5/ABC	838869	2010	2022	2028	Y	
5	G	South by Main Entrance	5/ABC	21280834	2021	2033	2027	Y	
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									

SIEMENS

FIRE EXTINGUISHER / HOSES INSPECTION REPORT

Building Name	Site Address	City
Miller Lash House	130 Old Kingston	SCARBOROUGH, ON
Date of Inspection	Job / Ticket Number	Lead Technician
October 25, 2023	UTSC - Campus Safety Inspection	UTSC - Byron Wilson

ITEM #	FLOOR#	LOCATION	DESCRIPTION	SERIAL #	MFG. DATE	NEXT H-TEST	NEXT 6 YEAR M	MAY 2023 Inspections	REMARKS
1	B	Across from the stairs	10/ABC	190210	2003	2027	2033	Y	RECOMMEND 2D SIGN
2	2	Top of Stairs	5/ABC	362284	2005	2029	2023	Y	RECOMMEND 2D SIGN
3	2	Bottom of Stairs to attic	2.5/ABC	346529	2013	2025	2031	Y	RECOMMEND 2D SIGN
4	G	East Adj. Exit by Fire Panel	5/ABC	596326	2003	2027	2033	Y	RECOMMEND 2D SIGN
5	G	North at Exit	5/ABC	412575	2013	2025	2031	Y	RECOMMEND 2D SIGN
6	G	West in Kitchen	5/ABC	21280798	2021	2033	2027	Y	RECOMMEND 2D SIGN
7	G	Outside in Maintenance Shed North	5/ABC	21280823	2021	2033	2027	Y	RECOMMEND 2D SIGN
8	G	Outside in Maintenance Shed North	5/ABC	21280821	2021	2033	2027	Y	RECOMMEND 2D SIGN
9	G	Valley Coach House	10/ABC	467196	2009	DUE		Y	DUE TO H-TEST
11									
12									
13									
14									
15									
16									
17									
18									
19									